



PORT OPERATIONS

Local Notice to Mariners 01/20 (Revision 4)

Tide buoys

Mariners are advised that due to storm damage the AADI (electronic current information from the buoy) is unavailable at the Eastern entrance. This will remain unavailable until the buoy can be lifted out of the water and repaired. **This Buoy has moved slightly South of its normal position due to the recent adverse weather.**

The other tide buoy (with the tide tails) has now been redeployed just East of the AADI buoy to avoid encroaching on the entrance.

In the interim, BA chart 1698 gives information on the predicted tidal streams at the Eastern entrance.

Steve Masters
Harbour Master

19th February 2020

Notices Remaining In Force:

- 08/19 – Decommissioned mooring equipment
- 11/19 – Rock armour SE corner of Wick Channel
- 23/19 - DWDR restricted Area
- 50/19 - Temporary Suspension of the Wick Channel Traffic Lights
- 01/20 – Tide Buoys (Revised)
- 05/20 – Over side Works ED7
- 06/20 - Diving Operations at ED2 and DCT East